Table of Contents

Certified Asphalt Producer Program Instructors Certified Asphalt Technician Training Course Agenda HMA Procedures and Policies Manual

Chapter One -- Introduction

| | Safety | 1-2 |
|------|---|------|
| | Terminology | 1-2 |
| | Technician Responsibilities | 1-3 |
| | Rounding | 1-3 |
| | Volumetrics | 1-5 |
| Chaj | pter Two Materials | |
| | Aggregates | 2-1 |
| | Sources | |
| | Physical Qualities | |
| | Stockpiling | |
| | Sampling | |
| | Size of Original Sample | |
| | Reducing a Sample to Test Size | |
| | Size of Test Sample (After Splitting) | |
| | Gradation | |
| | Certified Aggregate Producer Program | |
| | Asphalt | 2-31 |
| | Source and Nature of Asphalt | |
| | Performance Graded Binder | |
| | Asphalt Handling, Storage, and Sampling | 2-42 |
| | Handling | |
| | Storage | |
| | Sampling | |
| | Binder Volume | 2-47 |
| | Specific Gravity | |
| | Temperature Volume Relationships | |
| | Asphalt Supplier Certification Program | |

Chapter Three -- Hot Mix Asphalt Plant Operations

| Safety | 3-1 |
|--|--------|
| Similar Operations of Batch and Drum Plans | 3-4 |
| Cold Aggregate Storage and Feeding | |
| Dust Control and Collection Systems | |
| Hot Mix Asphalt Storage | |
| Batch Plants | 3-16 |
| Batch Plant Operations and Components | |
| Aggregate Cold Feed | |
| Aggregate Drying and Heating | |
| Screening and Storage of Hot Aggregate | |
| Introducing the Binder | |
| Pugmill Mixing | |
| Batch Plant Operation | |
| Plant Inspection Guidelines | |
| Drum Plants | 3-39 |
| Drum Mix Plant Components | |
| Aggregate Storage and Feed | |
| Binder Metering | |
| Aggregate Moisture Determination | |
| Drum Mix Operation | |
| Surge Bin and Weigh Scales | |
| Summary of Drum Mixers | |
| The Effect of Plant Type on HMA Properties | 3-50 |
| Batch/Wet Wash | |
| Batch/Baghouse | |
| Drum/Wet Wash | |
| Drum/Baghouse | |
| Aggregate Blending | . 3-51 |
| Design Mix Formula | |
| Method of Combining Aggregates | |
| Trial and Error Method | |
| Troubleshooting Hints | |
| Plant Inspection and Scale Check | 3-56 |
| Batch Plant | |
| Drum Plant | |
| Plant Calibration | 3-65 |
| Batch Plant | |
| Drum Plant | |
| Plant Troubleshooting | 3-73 |

Chapter Four -- Mix Design

| Mix Characteristics and Behavior | 4-1 |
|--|------|
| Bulk Specific Gravity or Density | |
| Air Voids | |
| Voids in the Mineral Aggregates | |
| Voids Filled with Asphalt | |
| Binder Content | |
| Plant Produced HMA | |
| Properties Considered in Mix Design | 4-6 |
| Stability | |
| Durability | |
| Impermeability | |
| Workability | |
| Flexibility | |
| Fatigue Resistance | |
| Superpave Mix Design Method | 4-11 |
| Aggregates | |
| Superpave Specimens | |
| Maximum Specific Gravity Mix | |
| Bulk Specific Gravity | |
| Dust Proportion | |
| Air Voids | |
| Voids in the Mineral Aggregate | |
| Voids Filled with Asphalt | |
| Recycled Materials | |
| Moisture Susceptibility | |
| Example Calculations | |
| Example Calculations | |
| Chapter Five Quality Assurance Procedures | |
| Chapter 11/0 Quality 120000 miles | |
| Random Numbers | 5-1 |
| Design Mix Formula | 5-3 |
| Lot/Sublot – QC/QA HMA | 5-3 |
| Acceptance Samples | 5-3 |
| Adjustment Period – QC/QA HMA | 5-9 |
| Mixture Acceptance | 5-9 |
| QC/QA HMA | |
| HMA | |
| Pay Factors – QC/QA HMA | 5-12 |
| Mixture | |
| Density | |
| Mix Appeal – QC/QA HMA | 5-16 |
| Adjustment Quantity – QC/QA HMA | 5-17 |
| Mixture Adjustment Factor | 5-18 |
| | - 10 |

Chapter Six -- Quality Control Procedures

| Producer | Personnel | 6-1 |
|--------------|--|------------|
| N | Management Representative | |
| | Certified Asphalt Technicians | |
| | ee Publications | 6-2 |
| | boratory | 6-3 |
| | ipment Calibration | 6-3 |
| - | | 6-4 |
| • | Sampling | 6-4 |
| | Aggregate/RAP Sampling | 0-4 |
| | Binder Sampling | |
| | <u>. </u> | |
| | HMA Sampling | |
| | HMA Sample Reduction | <i>(</i> 0 |
| | Testing | 6-8 |
| | Aggregate Testing | |
| | IMA Testing | |
| _ | cy of Tests | 6-10 |
| (| QC/QA HMA | |
| ŀ | HMA | |
| Adjustm | ent Period – QC/QA HMA | 6-11 |
| Control (| Charts – QC/QA HMA | 6-12 |
| A | Application | |
| (| Control Limits | |
| Т | Farget Mean Values | |
| | Control Chart Construction | |
| | Five Point Moving Average | |
| | Chart Interpretation | |
| | e to Test Results | 6-18 |
| | Control Charts | 0-10 |
| | Moisture Content | |
| | | 6-18 |
| | ric Control | 0-18 |
| | /MA | |
| | Air Voids | (22 |
| | roubleshooting | 6-22 |
| | Control Plan | 6-24 |
| Certifica | tion | 6-25 |
| | | |
| Appendix A I | Indiana Test Methods | |
| 207 | Sampling Stockpiled Aggregates | |
| | | |
| 571 | Quantitative Extraction of Asphalt/Binder and Gradation of Aggregate from HMA Mixtures | Extracted |
| 572 | Drying HMA Mixtures | |
| 578 | Qualification of a Surge Bin for Extended Storage | |

| 580 | Sampling HMA Mixtures |
|-----|---|
| 583 | Certified Volumetric Hot Mix Asphalt Producer Program |
| 586 | Binder Content by Ignition |
| 587 | Reducing HMA Samples to Testing Size |
| 802 | Random Sampling |
| 902 | Verifying Sieves |
| 903 | Verifying Ovens |
| 905 | Verifying Vacuum Systems |
| 906 | Verifying Mechanical Shakers |
| 908 | Calibrating Gyratory Compactors |
| 909 | Verifying Thermometers |
| 910 | Verifying Balances |

Appendix B -- AASHTO and ASTM Test Methods

AASHTO Test Methods

| R 30 | Practice for Mixture Conditioning of HMA |
|-------|--|
| PP 28 | Practice for Superpave Volumetric Desing for HMA |
| T 11 | Materials Finer Than 75 – μm (No. 200) Sieve in Mineral Aggregate by Washing |
| Т 27 | Sieve Analysis for Fine and Coarse Aggregates |
| T 40 | Sampling Bituminous Materials |
| T 166 | Bulk Specific Gravity of Compacted Bituminous Mixtures using Saturated Surface-Dry Specimens |
| T 209 | Theoretical Maximum Specific Gravity and Density of Bituminous Paving Mixtures |
| T 248 | Reducing Samples of Aggregate to Testing Size |

| T 255 | Total Moisture Content of Aggregate by Drying |
|-------|--|
| T 283 | Resistance of Compacted Bituminous Mixture to Moisture Induced Damage |
| T 312 | Preparing and Determining the Density of HMA Specimens by Means of the Superpave Gryatory Compactor |

ASTM Test Method

D 5821 Determining the Percentage of Fractured Particles in Coarse Aggregate

Appendix C -- Miscellaneous

Segregation Causes and Cures

Asphalt Content Diagnostic Chart

HMA Gradation Charts

Appendix D -- Quality Control Plans

Quality Control Plan

Quality Control Plan Checklist

Appendix E -- Audits

Certified HMA Producer Program Audit Checklist

Certified HMA Producer Program Partial Audit Checklist

Sampling, Sample Reduction, and Testing Procedures